

Opportunity / Fast Charging Tips



Use breaks and shift changes of 10 minutes or more to maximize your charging time.



Keep batteries above 30% state of charge for fast charging or 20% for opportunity charging to maximize their life.



Check connections frequently to make sure they are secure. Check for damaged cables or connectors that require replacement.



When charging, keep the battery compartment open to improve ventilation and cooling.



Never disconnect the battery from the charger without turning off the charger first.



After a break, choose the truck with the highest state of charge.



Make sure all batteries receive a weekly equalize charge to ensure peak performance.



Always check water levels after an equalize charge and top off as needed.



Contact your local Crown dealer for battery and charger service.